



THE ELECTRIC HEATER COMPANY

45 SEYMOUR STREET / P.O. BOX 288
STRATFORD, CT 06615-0288
TEL: (203) 378-2659 FAX: (203) 378-3593
<http://www.hubbellheaters.com>

SERVICE BULLETIN

Bulletin No. 003

Issue Date: August 18, 2006

Product: Model J Booster Heaters

Purpose: To provide field service technicians with specific information regarding product service or operation.

Background: The J Model Booster Heaters are now utilizing a new and improved T1000 Control Board and TD1000 Digital Display. Both components have been designed to further protect against water damage and enhance longevity. For J16 models a ribbon cable extension will also be supplied.

Current Status: Effective as of August 1, 2006 all booster heaters shipped from the factory will utilize the updated T1000 & TD1000.

Remarks/Action: To install the new TD1000 on existing J Models in the field, some retrofitting will be necessary. Please refer to replacement instructions for new TD1000 units, which is attached to this e-mail or call the factory for a copy.

There is no recall of these components and T1000 and TD1000 components should only be replaced when failed.

The original TD1000 is now obsolete. If you currently have inventory of this original component, please return them to Hubbell where we will replace them with the updated version.